

# WAX RECOMMENDATION

# **EVENT - UPDATED/REVISED!!!!!**

**Grand Travers Classic** Traverse City, Michigan Sunday, February 10<sup>th</sup> - 9 a.m. Start Time

Forecast: Saturday night low 4F. Overnight snow anticipated.

**Base Prep:** Clean skis with SWIX CH10 or SWIX Base Prep 99 - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

**Structure:** Extra fine .25 linear structure. Use SWIX Super Riller (T401) or a pair of skis with a fine or cold grind.

### GLIDE WAX - FAST

Race Wax: Apply SWIX CH4, scrape and brush using Medium Bronze Brush. Go for a short ski and polish with: Blue Nylon Polishing Brush (T0186B).

### GLIDE WAX - FAST

Base Prep Wax: Apply SWIX CH4, scrape and brush using Medium Bronze Brush.

Race Wax: Apply 1-2 additional applications of CH4 - consider using a new Fine Steel Brush (T0188B). Go for a short ski and polish with: Blue Nylon Polishing Brush (T0186B).

# GLIDE WAX - WICKED FAST

**Base Prep Wax:** Apply SWIX CH4, scrape and brush using Medium Bronze Brush. Apply 1-2 additional applications of CH4 - Consider using a **new Fine Steel Brush** (T0188B).

Race Wax: Apply SWIX LF4, scrape and brush using Medium Bronze Brush (T0158) Go for a short ski and polish with: Blue Nylon Polishing Brush (T0186B).

# KICK WAX

Base Kick Wax: Apply a thin layer of VR30 or VG35 Base Wax (iron in or use heat gun) & cork smooth. This layer will add durability and act as a cushion.

Race Wax: Apply multiple thin layers of VR30 or V05 Polar and cork in each layer. If extra grip needed cover with short thin layer of VR40 or V20 Green and cork smooth.

For detailed application instructions check out the Swix School of Waxing at

