

WAX RECOMMENDATION

EVENT: Hanson Hills Classic Grayling, Michigan - Sunday, March 2nd

Forecast: Saturday night low 15F.. Sunday temps rising quickly to 39F. Freezing rain possible. Rain possible in the afternoon.

Base Prep: Clean tips and tails with CH10, BP88 or BP99 - cool, scrape and brush using Course Bronze Brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

Structure: Use the SWIX T401 Super Riller and apply a .5 linear rill. Apply structure after waxing and brushing. Brush again: SWIX Blue Nylon Brush (T160).

GLIDE WAX - FAST

Base Race Wax: Apply CH7, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

GLIDE WAX - FASTER

Race Wax: Apply LF8, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

GLIDE WAX – WICKED FAST

Base Race Wax: Apply HF8, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

Race Wax: Race Wax: Apply FC8 Powder. FC8 is ironed in only ONCE during

application.Brush out with using SWIX Stiff Black Nylon Brush (T0194) or NEW SWIX Wild Boar (T0164). Final brush with SWIX Blue Nylon Brush (T0160). Or

Race Wax: Apply FC1 Solid with Iron for durability and brush out using Horsehair then Fine Nylon brushes.

* FC1 Solid could be hand-corked in and brushed out with Fine Nylon Brush

<u>Кіск Wax</u>

Base Kick Wax: Apply a thin layer of VG35 Base Wax (iron in or use heat gun) & cork smooth. This layer will add durability and act as a cushion.

Race Wax: Apply several layers of VR45 or V40 Blue Extra - cork in each layer. Cover with short layer of VR50 or V45 if extra grip needed & cork smooth. Freezing rain may require last minute adjustments for extra grip.

For detailed application instructions check out the Swix School of Waxing at

