



WAX RECOMMENDATION

EVENT: The Great Bear Chase - Sunday, March 9th
In Beautiful Calumet, Michigan (Home of Swedetown)

Forecast: Saturday night low around 6 degree F. Overnight snow anticipated.

Base Prep: Clean skis with SWIX CH10, BP88 or BP99 - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone of classic skis with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

Structure: Extra Fine Linear .25mm structure. Use SWIX Super Riller (T401).

GLIDE WAX - FAST

Race Wax: Apply SWIX CH4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis! Polish with SWIX Blue Nylon Brush (T160) after warm-up

GLIDE WAX - FASTER

Base Race Wax: Apply CH4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis!

Race Wax: Apply LF3, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Polish with SWIX Blue Nylon Brush (T160) after warm-up

Glide Wax - Wicked Fast

Base Race Wax: Apply SWIX LF4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis! Polish with SWIX Blue Nylon Brush (T160) after warm-up

KICK WAX

Base Kick Wax: Apply a thin layer of VG35 Base Wax (iron in or use heat gun) & cork smooth. This layer will add durability and act as a cushion.

Race Wax: Apply several layers of VR30 or V20 Blue Extra - cork in each layer. Cover with short layer of VR40 or V30 if extra grip needed & cork smooth.

For detailed application instructions check out the
NEW Swix Racing Website at: WWW.SWIXRACING.US

SWIX® racing.us