



WAX RECOMMENDATION

EVENT - 2008 Michigan High School Championships
Saturday, February 16th - BOYNE VALLEY LODGE

Morning Freestyle Races

Forecast: *Friday night low 1F. Overnight snow anticipated. Saturday temps rising to 20F during the afternoon. More Snow in the Forecast!*

Base Prep: *Clean skis with CH10 or BP99 - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper*

Structure: *Extra Fine linear: Swix Super Riller using the fine .25mm blade.*

GLIDE WAX - FAST

Base Race Wax: *Apply CH4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).*

GLIDE WAX - FASTER

Race Wax: *Apply LF4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).*

** Repeat above for even FASTER Skis!*

GLIDE WAX - WICKED FAST

Base Race Wax: *Apply LF4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish with SWIX Blue Nylon Brush (T160).*

** Repeat above for even FASTER Skis!*

Race Wax: *Apply LF3 Powder, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).*

** brush skis after on snow warm-up with SWIX Blue Nylon Brush*

**For detailed application instructions check out the
Swix School of Waxing at**

SWIX[®] **school.com**