

WAX RECOMMENDATION

EVENT

Garland Gripper Classic

Garland Resort, Lewiston, Michigan Saturday, January 19th - 11 a.m. Start Time

Forecast: Friday night low 11F. Overnight snow anticipated. Saturday morning temps may drop to about 10F by race time.

Ski Selection: Cold Base - fine structure

Base Prep: Clean skis with CH8 or SWIX Base Prep - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

GLIDE WAX - FAST

Base Race Wax: Apply CH4, scrape and brush using Medium Bronze Brush * Be sure to re-brush skis after your skis have cooled to outside temps

GLIDE WAX - FASTER

Base Race Wax: Apply LF3, scrape and brush using Medium Bronze Brush * Be sure to re-brush skis after your skis have cooled to outside temps

<u>GLIDE WAX – WICKED FAST</u>

Base Race Wax: Apply LF4, scrape and brush using Medium Bronze Brush * Be sure to re-brush skis after your skis have cooled to outside temps * If overnight temps stay in the low teens be ready to apply FC7 powder over the LF4!

KICK WAX

Base Kick Wax: Apply a thin layer of VG35 Base Wax or VR30 Light Blue(iron in or use heat gun) & cork smooth. This layer will add durability and act as a cushion.

Race Wax: Apply several layers of VR30 Light Blue (or V20 Green) and cork in each layer. Cover with a short layer of VR40 Blue (or V30 Blue) if extra grip needed and cork smooth.

For detailed application instructions check out the Swix School of Waxing at

