

# WAX RECOMMENDATION

EVENT – 2008 Michigan High School Championships SUNDAY, FEBRUARY 17<sup>TH</sup> – BOYNE VALLEY LODGE CLASSIC SPRINTS – Afternoon Finals!

**Forecast:** Saturday night low 18F. Overnight snow anticipated. Sunday temps rising to 31F during the afternoon. More Snow in the Forecast!

**Base Prep:** Clean skis with CH10 or BP99 - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

Structure: Fine linear: Swix Super Riller using the fine .33mm blade

### <u> Glide Wax - Fast</u>

Base Race Wax: Apply CH8, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

#### **GLIDE WAX - FASTER**

Race Wax: Apply LF8, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

#### **GLIDE WAX – WICKED FAST**

Base Race Wax: Apply HF8, scrape and using SWIX Stiff Black Nylon Brush (T0194) or NEW SWIX Wild Boar (T0164).

Race Wax: Apply FC8 Powder..FC8 is ironed only ironed in once during application. Brush out with using SWIX Stiff Black Nylon Brush (T0194) or NEW SWIX Wild Boar (T0164). Final brush with SWIX Blue Nylon Brush (T0160). Or

**Race Wax:** Apply FC1 Solid with Iron for durability and brush out using a SWOX Horsehair then Fine Nylon brushes.

\* FC1 Solid can also be hand-corked in and brushed out with Fine Nylon Brush

## KICK WAX

Base Kick Wax: Apply a thin layer of VG35 Base Wax (iron in or use heat gun) & cork smooth. This layer will add durability and act as a cushion.

**Race Wax:** Apply several layers of VR50 or V50 Violet & cork in each layer. Cover with short layer of VR55 or V55 Red Special if extra grip needed & cork smooth.

For detailed application instructions check out the Swix School of Waxing at

